

---

**Date:** February 2012

**Subject:** Pilot Unloader Valve (4004-00)

**Equipment:** Rockdusting

Pilot Unloader Valve 4004-00 is being replaced with part number P416X2. Since these parts are not identical, additional fittings may be required when retrofitting.

OLD 4004-00



NEW P416X2

